Model HW 102


Version:

Serial number: From week 01 of 2012

Code: 13142

20/11/2012

240 V - 50 Hz



Ansamblu CAPAC POMPA - 42734



Ans. POMPA COMPLETA
Poz. 30, cod 3641760



Motor
Poz 29, cod 3641810

Validity	Pos.	Code	Description	Q
	1	3640010	Green casing	1
	2	3082130	Water coupling kit	1
	3	3640050	Lock	1
	4	3640530	Extension	1
	5	3640190	Lock	1
	6	3640060	Lock	1
	7	3640030	Handle	1
	8	3640040	Plug	1
	9	3641160	Brush kit for motor	1
	10	3640580	Suction kit	1
	11	3641650	vezi info mai jos	1
	12	3640540	Electric pump assembly	1
	13	3640080	Bracket	1
	14	3640180	Bracket	1
	15	3640160	Conveyor	1
	16	3640170	Cover	1
	17	3641020	Cable	1
	18	3320200	Cable gland	1
	19	3320440	Switch	1
	20	3640020	Base	1
	21	3640620	Wheel	2
	22	3320054	Accessories carrier	1
	23	3640570	TSS kit	1
	24	3640560	Piston + seals kit	1
	25	3640550	Water seal kit	1
	26	3082661	Quick coupling	1
	27	3640610	Screw kit	1
	28	3640600	Detergent plug kit	1
	29	3641810	Motor	1
	30	3641760	Pump assembly	1

Model HW 102


Version:


Serial number: From week 01 of 2012

Code: 13142

20/11/2012

240 V - 50 Hz





Validity	Pos.	Code	Description	Q
	1	3320152	Gun	1
	2	3320130	Extension	1
	3	3640640	Lance+lance head	1
	4	3320120	Lance+rotopower	1
	5	3640090	Tank	1
	6	3640630	High pressure hose	1
	7	3641140	Gasket kit	1

UN_CE_0578-DU


TECHNICAL INFORMATION

2012/43

C12043

Subject	Outlet pump kit
For model	HW102
Country	Worldwide
Description	The pump outlet has been changed to a new system. If repair is needed, the pump outlet has optionally to be converting to the new pump repair kit.

Version until KW 52/2011




Old Version: The pump outlet is used with a bayonet connection to the pump

Pos. No.	Q'ty	Old part	Description	I/C	Pos. No.	Q'ty	New part	Description
11a	1	364 0590	Outlet pump kit	Yes ←	29	1	42 734	Pump repair kit

(I/C) The arrow ← shows, old part can only be replaced by new part.

If the outlet pump kit 364 0590 is discontinued, the pump repair kit 42 734 has to be used.

Version from KW 01/2012 or after repair with 42 734 Pump repair kit



New Version: Pump outlet is hold in position with a clamp

Pos No.	Part number	Q´ty	Description
11b	364 1651	1	Outlet pump kit

Remark	Please do not focus only on the year of manufacturing, but also to the present design version. **TIP: Generally, keep the o-rings of the quick couplings and the lances always slightly greased!**